


Air Cleaner Stud Replacement



Air cleaner assemblies for M1070 HET and M1074 and M1075 PLS tractors are not cheap, so it's tough to replace one just because a mounting stud is damaged or missing.

But, if the assembly doesn't seal correctly, the truck engine can be damaged, and that can be even more expensive.

So, keep the seal between the air cleaner mount and the element container tight by using stud replacement kit, NSN 5307-01-456-6938.

The kit contains one stud, one retainer and one washer. Order as many kits as you have damaged or missing studs.

